

PRE-BID ADDENDUM #1

06-Mar-18 Location	Window/Door Schedule			Operating Section Y/N	Notes
	Quantity	R.O. Width	R.O. Height		
Windows					
Education Wing, South, 1st Floor	4	125"	54 1/4"	Y, both ends	single hung
Education Wing, South, lower level	2	126 1/4"	41 3/4"	Y, both ends	single hung
Education Wing, North, 1st Floor	3	125"	54 1/4"	Y, both ends	single hung
Education Wing, N, 1st Flr, Nursery	1	72 1/2"	54"	Y, both ends	single hung
Kitchen	1	52 1/4"	29 3/4"	Y, both ends	single hung
North Wall inside shed	1	26 1/2"	54 1/2"	N	
Fellowship Hall, N, serving area	1	76 1/2"	52"	Y, both ends	single hung
Fellowship Hall, East	4	76 1/2"	29 3/4"	N	existing windows open
Fellowship Hall, East	1	100 1/2"	54 1/2"	Y, both ends	single hung
Sanctuary, main floor	4	60"	192"	N	block wall to block wall
Sanctuary, choir loft	2	24"	48"	Y	single hung
Doors					
	Door Hardware				
Education Wing, West Entrance	panic bar, outside handle w/lock, closer				
Education Wing, North stairwell to basement level, upper door	panic bar, outside handle w/lock, closer				
Education Wing, North stairwell to basement level, lower door	N/A				
Education Wing, N, exterior door into 1st floor shed	panic bar, outside handle w/lock, closer				
Education Wing, N, interior shed door from shed into bldg	no lock, push-pull only, closer				
Fellowship Hall, East fire exit door	N/A				
Sanctuary, East	panic bar, outside handle w/lock, closer				
Sanctuary, South	panic bar, no outside handle, closer				
Additional Addendum Items					
1. In the original RFP, the windows that open were called out to be single hung. Double hung and casement windows are also authorized.					
2. In the original RFP, there was no spec regarding the finish on the interior woodwork on the education and fellowship hall windows. The windows shall have a factory clearcoat finish applied to them. No tinted stain.					
3. All replacement doors, except the two sanctuary doors, will be full glass, 1" thermopane. Disregard the comment about being 1/4" tempered glazing in the original RFP.					
4. Include screens on all windows that open.					
					Tom Perry 362-4861